

Harry Brodhead

·1d·

Was out today for several hrs with the Director of Public Works and his Supervisor flushing main lines and street hydrants to try to nail down where all this danged discoloration is coming from. We are getting sediment from the wells that is going thru the Reverse Osmosis system. This should not happen. We originally thought it was sediment in the lines from previous issues that was washing thru the system. BTW- we also heard that Crystal River is having the start of a sediment problem as well.

We have ordered replacement pre-filters for delivery Mon or Tues. We found a supplier in Plant City that should have some and we are heading someone down there Monday am. However, we are still getting apparently fresh sediment thru the R.O. system probably related to several of the filter tubes damaged due to the exceptional drought and lowering of the water table. To stop any more damage to the RO system, we shut down our Water Plant and switched back to The Yankeetown Plant. We have made contact with the top RO expert and Chemical Engineer in the country (he is in California) and we are going to begin a Zoom conference call with him as soon as we install the new filters. I will have more info by Monday PM. Thanx, Harry B.